

30 Sept. 1943 Thursday.

- 0730 "yellow" to ops
0800 On duty Lt. Taylor.
0825 "Red" to ops.
Inspected airfield, runways + taxi lanes O.K.
0900 Inst. have been given to the clerk of the Works to clean up along main runway + fill in a few ditches.
1325 "yellow" to ops. -
Power will be off for about 10 min at 1400 hrs.
1505 1st wing request "ground" down to down.
1525 Mt. says ceiling 200 ft. viz 16000 -
1640 Issued camera IX to beacon crew.
1655 Wind S-SW - 11 mph.
1835 Inst. for flarepaths to be laid NE-SW.
1900 Beacon crew reports on site + flashing O.K.
2000 Insp. runways, flarepaths + taxi tracks. Replanned some red lines + had obstruction lights put around wrecked Halifax.
Mt. passes "yellow" aichrome + clearing in.
2330 all quit